

Descriptions: 1.3D magnetic flux meter acquire real-time magnetic field from three 3 phases, transfer the information to PC through RS232.

2.DC constant current power can be controlled the current on three phases on the panel, or by PC software.

3.The software can display magnetic field component from X.Y.Z three phase and resultant magnetic field.

4.Fluxmeter, constant current power and helmholtz coils are customized by our company.

5.PC can be desktop or notebook PC, through USB connect with constant power supply and fluxmeter, installed the control software.